

Special Process: Heat Treat System Assessment			
Facility Name:		MECLASA TERMIC,S.L.	
Address:			
C/GRANERA,66			
SANT LLORENÇ SAVALL(BARCELONA) SPAIN			
Phone Number:	34937140501	Type(s) of Thermal Processing at this Facility:	
Fax Number:	34937141080		
Number of Heat Treat Employees at this Facility:		Process Table A - Ferrous	
		Carburizing	
9 EMPLOYEES		Carbonitriding	
		Carbon Restoration	
Internal (Captive) Heat Treater (Y/N):	YES	Neutral Hardening (Quench and Temper)	
Commercial Heat Treater (Y/N):	YES	Austempering / Martempering X	
Date of Assessment:		Tempering X	
		Precipitation Hardening / Aging	
Date of Previous Assessment:		23-May-2018	
		Process Table B - Ferrous	
		Nitriding (Gas)	
		Ferritic-Nitrocarburizing (Gas or Salt)	
		Process Table C - Aluminum	
		Aluminum Heat Treatment	
		Process Table D - Ferrous	
		Induction Heat Treating	
		Process Table E	
		Annealing	
		Normalizing	
		Stress-Relieving	
		Process Table F	
		Low Pressure Carburizing	
		Process Table G	
		Sinter Hardening	
		Process Table H	
Ion Nitriding			
Current Quality Certification(s):	29/09/2019		
Date of Re-assessment (if necessary):			
Personnel Contacted:			
Name:	Title:	Phone:	Email:
Jaume Busquets	Direction Commercial	937140501	info@meclasatermic.com
Pere Fernández	Direction Quality	637877018	pere.fernandez@meclasatermic.com
Auditors/Assessors:			
Name:	Company:	Phone:	Email:
Julio del Rio	jdrconsultoria	692633913	juliodelrio@jdrconsultoria.com
Number of "Not Satisfactory" Findings:			
1			
Number of "Needs Immediate Action" Findings:			
Number of "Fail" Findings in the Job Audit(s):			